

Master Walk-Through Checklist and Look-Fors-Attachment for walk-through November 21, 2016

Number 8. Ceiling tiles present; no broken, stained, or painted

Location	Fixed	Comments
Front 6 th grade Upper Stairwell by doors		
Back 6 th grade Upper stairwell		
Room 14 Hallway by smoke detector		
Room 9 Hallway chipped		
Room 8 hallway		
Room 1 cracked tile		
Conference Room Hallway tile near speaker, small tile by sprinkler head, and tile next to sprinkler head		3 different tiles
Main Foyer/Cove 2 tiles: between lights and in cove		2 different tiles
7 th grade front stairwell tile around sprinkler head		
Mechanical Room 2 just outside door		
7 th grade front bottom stairwell tile near light fixture, above interior doors, and tile above "office" sign		3 different tiles
Downstairs hallway by elevator chipped tile near speaker		
Tile above water fountain near elevator needs adjustment, across from water fountain tile cracked		2 different tiles
Room 35 Hallway, hole in tile		
7 th grade staff back bathroom ceiling tile		
Room 40 Hallway smoke detector and tile by interior doors to stairwell		2 different tiles
Room 43 hallway two tiles near sprinkler head		2 different tiles
Room 45 hallway two tiles near sprinkler head/light fixture		2 different tiles
6 th grade hallway transition to media center cracked tile		
6 th grade hallway to stairwell, tile near classroom window		
Cafeteria Atrium cracked and stained tiles		3 different tiles
Park and Recs. Room, clear tape on sprinkler, tiles stained by bathroom and bulletin board		2 different tiles
PTA Closet		2 different tiles

